
Week 33 Unattended Noise Monitoring Reports

Summary of Weekly Noise Data and Exceedances of Permissible Levels






<u>Notes</u>
There was 1 exceedance of the construction noise limits at the Mary's Terrace position.

There was 1 exceedance of the construction noise limits at Cole Park Road (Footbridge). Both exceedances were not site related but due to a helicopter flying overhead.

- Measured LAeq.1hr Averaged noise levels over 1-hour period.
- Measured period LAeq, T The line shown on the graph follows the averaged Leq level over the relevant assessment period (i.e. Monday 08:00-18:00hrs LAeq, 10h,
- or Saturday 08:00-13:00hrs LAeq,5h). When an exceedance occurs, the noise level over a measured period goes above the Construction Noise Level (CNL) limit.
- Construction Noise Level (CNL) limits.

MP1 - Mary's Terrace: Time History Graph



MP2 - Cole Park Road (site boundary): Time History Graph

