

# Week 38 Unattended Noise Monitoring Reports



## Summary of Weekly Noise Data and Exceedances of Permissible Levels


between 07:00 hours Monday 16 September 2019 and 07:00 hours Monday 23 September 2019

### Notes

There were 3 exceedances of the construction noise limits during this week of monitoring at the Mary's Terrace Platform 5 gate monitoring location. These exceedances were all due to a MEWP engine during night time works. It should be noted that the noise monitor is located at the boundary of the site premises, 15 metres from the nearest residential receptor (16 Mary's Terrace). There were 0 exceedances at the Cole Park Road monitoring position.

- Measured LAeq,1hr - Averaged noise levels over 1-hour period.
- Measured period LAeq,T - The line shown on the graph follows the averaged Leq level over the relevant assessment period (i.e. Monday 08:00-18:00hrs LAeq,10h, or Saturday 08:00-13:00hrs LAeq,5h). When an exceedance occurs, the noise level over a measured period goes above the Construction Noise Level (CNL) limit.
- Construction Noise Level (CNL) limits.

### MP1 - Mary's Terrace Platform 5 gate: Time History Graph



### MP2 - Cole Park Road: Time History Graph

